

Pipeline Integrity Direct Assessment DONE RIGHT.

Pipeline Integrity Assessments

- External Corrosion Direct Assessment (ECDA)
- Internal Corrosion Direct Assessment (ICDA)
- Microbial Induced Corrosion Evaluations (MIC)
- Stress Corrosion Cracking Direct Assessment (SCCDA)
- pH Measurements
- Dent and Mechanical Damage Assessment
- ILI Tool Validation
- Remaining Strength Calculations (RSTRENG)
- Cathodic Protection Pipe to Soil Readings
- ILI Tool Validation

Inspection and Testing Techniques

- UT-SW & PAUT Ultrasonic Inspections
- Full Matrix Capture (FMC)
- Total Focus Method (TFM)
- Time of Flight Diffraction (TOFD)
- Magnetic Particle Testing (MT)
- Guided Wave
- Coating Evaluation (NACE)
- Positive Material Identification (PMI)
- Weld Inspections
- Corrosion Mapping
- Creaform Laser Scanning



American
Petroleum
Institute

Highly Skilled Technicians Focused on Efficiency and Quality

With over 50 skilled experts excelling in advanced NDT and inspection techniques, and a comprehensive understanding of pipeline operations, our PLI technicians efficiently manage time at dig sites, adhere to your procedures, and promptly update teams on obstacles or potential variances during operations.

Unmatched Proficiency and Dedication to Ensuring Pipeline Safety & Security

Our PLI division serves leading pipeline operators with PHMSA guidance & compliance. Continuously refining strategies per the PHMSA Megarule, we're committed to fast, flexible & accurate solutions while remaining technology-agnostic. By collaborating with key inspection equipment providers, we deliver comprehensive, cost-effective, and accurate project outcomes.



GET IN TOUCH

nvindt.com
Office: 985.876.5559
Toll Free: 877-NDT-NVI1
Fax: 985.876.9355

CORPORATE OFFICE
2449 W. Park Ave.
P.O. Box 1690
Gray, LA 70359

Lafayette, LA • New Iberia, LA • Sulphur, LA
Odessa, TX • Aransas Pass, TX • Carthage, TX
Houston, TX • Carlsbad, NM • Burgettstown, PA
Northglenn, CO • Theodore, AL • Superior, WI

Scan to
Learn More